


Coffs Harbour

Visual impact photomontage and methodology report 7th March 2025

Prepared by Arterra Interactive

MAP OF 3D CAMERA LOCATION



PHOTOGRAPH SHOWING CURRENT CONDITION AND PROPOSED DEVELOPMENT



VIEWPOINT POSITION 02A

PHOTOGRAPH SHOWING CURRENT CONDITION AND PROPOSED DEVELOPMENT



VIEWPOINT POSITION 02B

PHOTOGRAPH SHOWING CURRENT CONDITION AND PROPOSED DEVELOPMENT



PHOTOGRAPH SHOWING CURRENT CONDITION AND PROPOSED DEVELOPMENT



PHOTOGRAPH SHOWING CURRENT CONDITION AND PROPOSED DEVELOPMENT



VIEWPOINT POSITION 05A

PHOTOGRAPH SHOWING CURRENT CONDITION AND PROPOSED DEVELOPMENT



VIEWPOINT POSITION 05B

PHOTOGRAPH SHOWING CURRENT CONDITION AND PROPOSED DEVELOPMENT



PHOTOGRAPH SHOWING CURRENT CONDITION AND PROPOSED DEVELOPMENT



PHOTOGRAPH SHOWING CURRENT CONDITION AND PROPOSED DEVELOPMENT



PHOTOGRAPH SHOWING CURRENT CONDITION AND PROPOSED DEVELOPMENT



PHOTOGRAPH SHOWING CURRENT CONDITION AND PROPOSED DEVELOPMENT



PHOTOGRAPH SHOWING CURRENT CONDITION AND PROPOSED DEVELOPMENT



PHOTOGRAPH SHOWING CURRENT CONDITION AND PROPOSED DEVELOPMENT



VIEWPOINT POSITION 12A

PHOTOGRAPH SHOWING CURRENT CONDITION AND PROPOSED DEVELOPMENT



VIEWPOINT POSITION 12B

PHOTOGRAPH SHOWING CURRENT CONDITION AND PROPOSED DEVELOPMENT

