

Investigation site boundary (source: LPI)

Contour 1m (source: LiDAR)

Slope exceeding 18 degrees (source: LiDAR)

Endangered ecological community (EEC)





Disclaimer: The mapping is indicative of available space and location of features which may prove critical in assessing the viability of the proposed works. Mapping has been produced on a map base with an inherent level of inaccuracy, the location of all mapped features are to be confirmed by a registered surveyor.



15/07/2021 Issue 1

1:2,000 @A3 GDA 1994 MGA Zone 56



Threatened Species & EECs - Site 2